

W02015A-03-0724

Arizona Department of Environmental Q
Water Quality Compliance Assurance U
 1110 W. Washington Street, 5415B-1
 Phoenix, AZ 85007



0000036678

57

11 10
 Supplement from
 ADEQ
 Will submit
 Edgar m. Nelson

ORIGINAL

Drinking Water Compliance Status ReportPublic Water System Name: Beaver Valley Water Co.Public Water System ID #: 04-004Public Water System Type: ☒ CO ☐ Non-transient Non-community ☐ Transient Non-communityOverall Compliance Status: ☐ No Major Deficiencies ☒ Major DeficienciesMonitoring and Reporting Status: ☐ No Major Deficiencies ☒ Major Deficiencies**Comments:**

This system has failed to provide calendar year 2004, consumer confidence report by July 1, 2005.

The ADEQ data base does not show that any of the required annual TTHM, HAA5 or monthly chorine residual analysis has been done for this water system.

Operation and Maintenance Status: ☒ No Major Deficiencies ☐ Major Deficiencies**Comments:****Major unresolved/ongoing operation and maintenance deficiencies:**

- | | |
|---|---|
| <input type="checkbox"/> unable to maintain 20psi | <input type="checkbox"/> inadequate storage |
| <input type="checkbox"/> cross connection/backflow problems | <input type="checkbox"/> surface water treatment rule |
| <input type="checkbox"/> treatment deficiencies | <input type="checkbox"/> approval of construction |
| <input type="checkbox"/> certified operator | <input type="checkbox"/> other |

Date of last inspection / sanitary survey: 11-22-00**Administrative Orders:**Is an ADEQ administrative order in effect? ☐ Yes ☒ No**Comments:****System information:**Number of Points of Entry 1 Number of Sources 2 Population Served 350Service Connections 170 Initial Monitoring Year 1993 Initial MAP Year 1999AZ CORP COMMISSION
DOCUMENT CONTROL

2005 NOV -8 P 1:39

RECEIVED

Evaluation completed by: Jim PuckettPhone: 602-771-4649Date: 7-5-05

Because of the previously identified compliance monitoring deficiencies, ADEQ cannot determine that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.